

Airworthiness Directive Schedule

Aeroplane

PZL M18B "Dromader"

25 September 2003

- Notes**
1. This AD schedule is applicable to the PZL M18B Dromader manufactured by Wytownia Sprzetu Komunikacyjnego "PZL-Mielec" under Type Certificate Swiadectwo Typu Sprzetu Lotniczego Nr BB-120.
 2. The date above indicates the amendment date of this schedule.
 3. New or amended ADs are shown with an asterisk *

Contents

*DCA/PZLM18/1	Seat Belt - Inspection	2
---------------	------------------------------	---

***DCA/PZLM18/1 Seat Belt - Inspection**

Applicability: All Model M18 Dromader

Requirement: To detect incorrect attachment of the belt length adjusters, which may cause the seatbelts to fail under load in the event of a crash landing, inspect per PZL Mandatory Bulletin No. E/02.184/2003.

(Polish Civil Aviation Office AD Nr SP0010-2003-D)

Compliance: Within next 100 Hours TIS or 12 months whichever occurs first.

Effective Date: 25 September 2003